



+5V
 -5V
 +12V
 L
 CS2
 CSF
 DRAIN
 MUX
 RAS
 CAS
 DRAIN
 MUX
 A15
 A14
 A13
 A12
 A11
 A10
 A9
 A8
 A7
 A6
 A5
 A4
 A3
 A2
 A1
 A0
 D7
 D6
 D5
 D4
 D3
 D2
 D1
 D0

C82
 C81
 IO-33
 MH 32 16
 IO-34
 MH 32 16
 IO-35
 MMB 8708
 (I 2716, I 2732)
 IO-36
 UCY 74 157
 IO-37
 UCY 74 157
 IO-38
 MH 32 05
 MH 74 504
 IO-40
 MH 74 504